UAV MISSION REPORT

Prepared for: Morgan Lee • Cedar Ridge Properties

Completed By	Andrew	**Mission Number**	2043_101326_4
Date	10/13/26	**Total Flight Time**	32 min 50 sec
Start Time	0910	**Number of Flights**	2
End Time	1002		

MISSION

Nature	Inspection	**Requestor**	Morgan Lee — Roof Inspection
Organization	Cedar Ridge Properties	**Quote #**	Q-261017-001

CREW & AIRCRAFT

RPIC	J. Ellis	**Visual Observer**	T. Reed
Aircraft	Mavic - 1 — DJI Mavic 3	**FAA Registration**	DEMO_1
Remote ID Serial	DEMO_007	**Internal Asset**	Mavic - 1

LOCATION & CONDITIONS

Address	3734 Elvis Presley Blvd, Memphis, T…	**Lat / Long**	35.0468216, -90.0242325
Airspace	B	**Nearest Airport**	MEM — Frederick W Smith Intl/Mem…
Distance	2.7 miles	**FAA Grid Ceiling**	0 ft AGL · informational

MISSION DETAILS

Media	46 photos and 3 videos captured	**Media Notes**	Rooftop surface, equipment, drains.
Weather / Visibility	Cloudy, 54°F, wind N 14 mph, visibil…	**Weather Source**	National Weather Service · KMEM, 2…

DEMO

MISSION DESCRIPTION

2043_101326_4

On October 13, 2026, at approximately 9:00 PM, an aerial inspection was conducted for Morgan Lee of Cedar Ridge Properties at 3734 Elvis Presley Blvd, Memphis, TN, 38116. The operation consisted of 2 flights with a total flight time of approximately 33 minutes. The photos and video were provided via email for the customers review.

DEMO

PREFLIGHT REVIEW

2043_101326_4

RPIC	J. Ellis
Checklist	Complete
Aircraft	Mavic - 1 — DJI Mavic 3
Weather Conditions	Cloudy, 54°F, wind N 14 mph, visibility 10 mi
Airspace	B
Nearest Airport	MEM — Frederick W Smith Intl/Memphis

AIRCRAFT

- ✓ Aircraft visually inspected
- ✓ Propellers secure and undamaged
- ✓ Flight battery installed and adequate
- ✓ Controller and device charged
- ✓ Aircraft system ready
- ✓ Remote ID status reviewed

SITE & AIRSPACE

- ✓ Launch and recovery area reviewed
- ✓ Airspace reviewed
- ✓ Required authorization confirmed
- ✓ Obstacles identified
- ✓ People and vehicles considered
- ✓ Flight path reviewed

OPERATIONAL READINESS

- ✓ RPIC readiness reviewed
- ✓ Crew briefed, if applicable
- ✓ Comm's Plan confirmed
- ✓ Emergency procedures reviewed
- ✓ Required documents available

RPIC NOTES

Work area checked for people and obstacles.

DEMO

QUOTE

Q-261017-001

PREPARED FOR

Morgan Lee

Cedar Ridge Properties

3734 Elvis Presley Boulevard, Memphis, TN

QUOTE DATE

Oct 17, 2026

VALID UNTIL

Nov 16, 2026

Roof Inspection

Inspection

Inspection of roof and rooftop HVAC equipment.

DESCRIPTION	QTY / MI	RATE	AMOUNT
Roof Inspection	1	$175.00	**$175.00**

Subtotal	**$175.00**
Discount	**–$17.50**
Tax	**$14.57**
TOTAL	**$172.07**

DEMO